OFFICECONNECT® CABLE/DSL ROUTER 3COM FIRMWARE VERSION 1.031 RELEASE NOTES

Legal Rights

IMPORTANT: READ THIS BEFORE INSTALLING OR USING THIS SOFTWARE

You should carefully read the terms and conditions of the Software License Agreement. This text is contained in a file called license.txt. Your legal rights are defined therein.

USE OF THIS SOFTWARE INDICATES THAT YOU ACCEPT SUCH TERMS AND CONDITIONS. IF YOU DO NOT AGREE WITH SUCH TERMS AND CONDITIONS, DO NOT USE THIS SOFTWARE.

Related Documentation

Use these notes in conjunction with the following documents:

- OfficeConnect Cable/DSL Router User Guide (part number DUA8589-1AAA01)
- OfficeConnect Cable/DSL Router Installation Guide (part number DIA8589-1AAA01)

Known Issues with This Release

The following are issues that have been identified in this release:

- L2TP/IPSec tunnels cannot co-exist with IPSec tunnels.
- L2TP/IPSec supports only one tunnel at any time.
- If an IPSec tunnel is set for IP=ANY, then that tunnel will be the only one permitted. All other tunnels will not work.

3Com World Wide Web Site

Download the latest firmware for your Router and access the latest networking information on the 3Com Corporation World Wide Web site by entering our URL into your Internet browser:

http://www.3com.com/

Copyright © 2004-2005, 3Com Corporation. All rights reserved.

Unless otherwise indicated, 3Com registered trademarks are registered in the United States and may or may not be registered in other countries.

3Com, OfficeConnect, and the 3Com logo are registered trademarks of 3Com Corporation. Windows is a registered trademark of Microsoft Corporation. Other brand and product names may be registered trademarks or trademarks of their respective holders.

Part No. DNA8589-1AAA02 Published January 2005